

## SURFACE AUDIT

### Zone 4 - Buxton Road/King Street/Union Street / Belle Vue Road



1. View along the Channel.




2. Mix of patchy tarmac, stone flags, stone setts and kerbs at southern end of Buxton Road (north).



3. Tarmac area fronting 'Brambells' with some stone setts to road side (south).



4. Area to north of Conservation Area boundary- mainly tarmac but with some stone setts fronting the Church.



5. Attractive coursed setts (a mix of gritstone and limestone, located to the northern edge of the conservation area boundary).





*As above - Detail of pattern formed by the use of square limestone and gritstone setts alongside gritstone setts laid lengthways.*

---



*Detail of robust stone kerb detail on Buxton Road, alongside narrow concrete kerb and tarmac.*

---



*6. Unattractive broken concrete apron to properties at the junction with King Street (north).*


---



*7. Yorkstone flags and sett detail corner of Buxton Road and King Street.*

---





**KEY**

- Zone Boundary
- Setts (Gritstone and Limestone)
- Tarmac
- Pebbles/Cobbles
- Flags (Concrete)
- Flags (Gritstone)
- Bricks/Brick Paviers
- 1 Photographs

Predominant Surfacing :-

- \* Artificial
- Tarmac
- Paving Flags
- Concrete Kerbs

**ASHBOURNE  
CONSERVATION AREA**

**ANALYSIS OF CHARACTER  
SURFACE AUDIT**

**ZONE 4**  
Buxton Road, King Street,  
Union Street and Belle Vue Road

**FIG 21**

This map is reproduced from the Ordnance Survey material with the permission of Ordnance Survey on behalf of the Controller of Her Majesty's Stationery Office © Crown copyright. Unauthorised reproduction infringes Crown copyright and may lead to prosecution or civil proceedings. (100019785) 2007 Derbyshire Dales District Council.